

# CONTROL SURVEY MONUMENT RECOVERY

Cathedral City

Date Printed: 10/01/2003

<b>Number: 603</b> <b>Name: RM 53</b>
--

<b>Monument Description:</b> GPS Useable: 2.5" Brass disk in concrete curb  Stamping: RM 53 Center Mark: Recovery By: RM                      Date:
<b>Location:</b> Southeasterly return of Frank Sinatra Dr. and Morningside Dr  At the easterly E.C.R.
<b>Notes:</b> 250.48 per R.M.



<b>NAD 83 Coordinates</b>	<b>Epoch:</b>	<b>Accuracy: Scaled</b>	<b>Survey by:</b>	<b>Adj.:</b>	
<b>Ellipsoidal Coordinates, GRS 80</b>		<b>Horizontal Coordinates</b>		<b>CCS 83, Zone 6 Coordinates</b>	
	Deg.	Min.	Seconds	Meters	US Survey Feet
Latitude	33	46	21.00000	Northing:	
Longitude	116	25	31.00000	Easting:	
Ellipse Height (m):				Grid Scale:	
				Height Scale:	
				Combined Factor:	

Elevation (MSL)	Meters	Feet	Epoch Date	Survey By	Adj. Date	Accuracy
<b>NAVD88:</b>	77.045	252.770	1991.5	RBF	March 1997	Second, I
<b>NGVD29:</b>		250.460		RBF	March 1997	Second, II